

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2019

Submitted Date:

01/23/2019

Document Number:

692601224**FIELD INSPECTION FORM**

Loc ID 426163 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg | (970) 630-3909 | greg.jones@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 426176 | WELL | PR | 03/11/2012 | GW | 125-12024 | Rockwell 24-13A 1S45W | PR |

General Comment:Routine Inspection

| Location | | | | |
|--|--|--------|--|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Trail through farm ground | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | OTHER | | | |
| Comment: | Lease signs mounted to meter shed | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Lease sign mounted to fence at unit | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | OTHER | | | |
| Comment: | Metal panels around meter shed and VGS | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Metal panels around wellhead | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Gas Meter Run | # 2 | | | corrective date |
| Comment: | Shared meter run for Rockwell 24-13A and 24-13B 420' southwest of wellhead on north side of CR | | | |
| Corrective Action: | | | | Date: |
| Type: Progressive Cavity | # 1 | | | |
| Comment: | Weatherford cavity pump | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | # 3 | | | |
| Comment: | Electric panel, control panel and telemetry equipment at meter shed | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------------|--|-------|--|
| Type: Vertical Separator | # 2 | | |
| Comment: | 2-Vertical gas separators 50% buried by meter shed | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 426176 | Type: | WELL | API Number: | 125-12024 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Rockwell 24-13A and 24-13B) 420' SW of wellhead on north side of CR 27 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT