

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 460722



WC-4 Vault Point of release



3/8" Stainless steel process piping that separated and was point of release. Line repaired in picture with coupler