

Final Reclamation and Stormwater Inspection

January 21, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 410164

Inspection Document #: 674902460

Weld County, CO

SENE Section 28 T3N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /3N68W28

Location ID: 410164



Photo 1. Photo taken from the access road of CR 7, facing West. Appears the Operator has performed final reclamation activities with the evidence of drilling rows and straw crimped mulch.



Photo 2. Photo taken from the access road of Stallion Way, facing North. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /3N68W28

Location ID: 410164



Photo 3. Photo taken from the location, facing Northwest. See comments from Photo 1.



Photo 4. Photo taken from the location. See comments from Photo 1.

Inspection Photos
Location Name: CRESTONE PEAK RESOURCES /3N68W28
Location ID: 410164



Photo 5. Photo taken from the location. Note the remaining equipment that should have been removed per Rule 1004 by 7/25/2018 according to the last inspection.



Photo 6. Photo taken from the access road, facing North. See comments from Photo 1.