

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)

Inspection Date: 1/09/2019



Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)
Inspection Date: 1/09/2019



Photo # - 2

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)

Inspection Date: 1/09/2019



Photo # - 3

Shorty #1 separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)
Inspection Date: 1/09/2019



Photo # - 4

Shorty #1 meter shed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)
Inspection Date: 1/09/2019



Photo # - 5

Shorty #1 tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)

Inspection Date: 1/09/2019



Photo # - 6

Shorty #1 tank battery crude oil tank leak



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Western Operating Co. – Shorty #1 Tank Battery (Location ID 313944)

Inspection Date: 1/09/2019



Photo # - 7

Shorty #1 tank battery crude oil tank leak



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources