

Inspection Photos

Location Name: ANT HILL UNIT 28-44

Location ID: 05-103-10221

Inspection: 679702729



Photo 1. Location looking north.



Photo 2. Hole in tank battery liner.

