

Inspection Photos

Location Name: WRD UNIT 28-31

Location ID: 05-103-10142

Inspection: 679702733



Photo 1. Location looking south.



Photo 2. Separator stack without bird protection.

