

Inspection Photos  
Location Name: UPRR 23 Pan AM L#1  
Location ID: 319929



Photo 1 TNK BTRY

Photo 2 WH

**Inspection Photos**  
**Location Name: UPRR 23 Pan AM L#1**  
**Location ID: 319929**



**Photo 3 Unused equipment**



**Photo 4 Mechanical Leak**

**Inspection Photos**  
**Location Name: UPRR 23 Pan AM L#1**  
**Location ID: 319929**



**Photo 5 Unused equipment**