

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2019

Submitted Date:

01/18/2019

Document Number:

681701166

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Arauza, Steven 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brannon, Ginny		ginny.brannon@state.co.us	CDRMS
Leonard, Mike		mike.leonard@state.co.us	
Morgan, Kelly		kelly.morgan@state.co.us	CDPHE
Deranleau, Greg		greg.deranleau@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
,		cogcc.inspections@caerusoilandgas.com	
McKee, Michael	720-880-6322	mmckee@caerusoilandgas.co	EHS; All Inspections
Murray, Richard		g.richard.murray@state.co.us	
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460722	SPILL OR RELEASE	AC	01/16/2019		-	Basin Pipeline WC-4 Vault Release	EI

General Comment:

COGCC joint inspection with EPS S. Arauza and Western Integrity Inspector R. Murray. Follow-up to eForm 19 Spill/Release Report (doc #401905874, Spill/Release ID #460722).

Met with B. Middleton, B. Rollins, and R. Koenke of Caerus Piceance LLC to discuss spill/release of produced water from Basin Pipeline WC-4 Vault including initial response efforts, delineation of impacts, and remediation options. Operator's representatives guided COGCC inspectors along the ~1,400' length of the flow path, which extends from the point of release (POR) located north of the Orchard Compressor Station to a gravel pit (part of the Una Pit Complex) located south of Caerus' Tipping OD 34 pad (Location ID #334094). See photos.

On inspection date, operator was advised to provide additional spill notification to CDPHE for impacts to surface water (gravel pit) and to the Local Governmental Designee as well as to submit an eForm 19 Spill/Release Report. Operator provided CDPHE and LGD notification while submitting the eForm 19 Spill/Release Report (doc #401905874) on the same day. Additional spill documentation is provided under Spill/Release ID #460722.



Environmental**Spill/Remediation:**

Comment: Oil/condensate stained soil and released fluids observed outside of produced water vault/POR on inspection date. See photos. Supplemental eForm 19 Spill/Release Report due within 10 calendar days of discovery date, per Rule 906.b. Operator was instructed to submit an eForm 27 Site Investigation and Remediation Workplan and to remove and properly dispose of oily waste, per Rule 907.e., via phone on 1/17/2019.

Corrective Action: Submit an eform 27 Site Investigation and Remediation Workplan.

Date: 01/31/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401910459	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707611
681701169	20190115 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707610