

Inspection Photos

1/17/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 384906

Inspection Doc. Number: 682504426

Kiowa County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: 2017 Google Earth aerial image. Photo shows areas of the location (red polygon, 4.11 acres) where vegetation has not achieved a uniform desirable perennial vegetative cover. Photo also shows access road (blue, 434 feet). Access road remains predominantly bare and exposed soil.



Photo 2: Photo taken from the access road east of the location, facing west. Photo shows access road remains predominantly bare and exposed soil.



Photo 3: Photo taken from the access road on the east end of the location, facing west. Photo shows location remains predominantly undesirable weedy plant species (Russian thistle) or bare and exposed soils.



Photo 4: Photo taken from the access road on the east end of the location, facing west. Photo shows location remains predominantly undesirable weedy plant species (Russian thistle) or bare and exposed soils.



Photo 5: Photo taken from the access road on the east end of the location, facing northwest. Photo shows location remains predominantly undesirable weedy plant species (Russian thistle) or bare and exposed soils.



Photo 6: Photo taken from the north end of the location, facing east. See comments under photo 3.



Photo 7: Photo taken from the north end of the location, facing south. See comments under photo 3.



Photo 8: Photo taken from the north end of the location, facing southwest. See comments under photo 3.



Photo 9: Photo taken from the north end of the location, facing west. See comments under photo 3.



Photo 10: Photo taken from the southwest end of the location, facing northeast. See comments under photo 3. Vegetation observed in photo is sand dropseed. Desirable vegetation is sparse and not uniform.



Photo 11: Photo taken from the southwest end of the location, facing east. See comments under photo 3. Vegetation observed in photo is sand dropseed. Desirable vegetation is sparse and not uniform.



Photo 12: Photo taken from the south end of the location, facing northwest. See comments under photo 3.



Photo 13: Photo taken from the south end of the location, facing north. See comments under photo 3.



Photo 14: Photo taken from the south end of the location, facing northeast. See comments under photo 3.



Photo 15: Photo taken from the central area of the location. Photo shows location remains predominantly bare and exposed soils or undesirable weedy plant species. Yellow colored vegetation seen in photo Sand Dropseed. Any desirable vegetation on location is sparse and not uniform.



Photo 16: Photo taken from the adjacent reference area. Vegetation observed included Sand Draopseed, Blue grama, Western Wheatgrass, Sand Sage, Purple threeawn, etc... Photo shows location is not reflective of the reference areas.