

# Inspection Photos

1/17/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 430807

Inspection Doc. Number: 682504436

Kiowa County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



**Photo 2:** Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.



**Photo 3:** Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



**Photo 4:** Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.



**Photo 5:** Photo taken from the adjacent reference area. Photo shows reference area vegetation.



**Photo 6:** Photo taken from access road, facing north. Photo shows section of access road that has not achieve uniform vegetation.



**Photo 7:** Photo taken from access road, facing south. Photo shows section of access road that has not achieve uniform vegetation.