

# Inspection Photos

1/17/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 440886

Inspection Doc. Number: 682504441

Kiowa County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: BAYHORSE PETROLEUM LLC - 10234  
Location ID: 440886



**Photo 1:** 2012 google earth aerial image. Photo shows area prior to oil and gas disturbance. Note access road did not pre-exist oil and gas location.



Inspection Photos  
Operator: BAYHORSE PETROLEUM LLC - 10234  
Location ID: 440886



**Photo 1b:** 2015 google earth aerial image. Photo shows area of the location and access road disturbance mapped on the ground by inspector with a GPS. Mapped disturbance of location is ~3.78 acres, access road is ~3,500 by inspector.





**Photo 2:** Photo taken from the west end of the location, facing north. Photo shows location remains predominantly bare and exposed soil. Desirable vegetative establishment does not appear to be progressing towards reclamation standards.



**Photo 3:** Photo taken from the west end of the location, facing northeast. See comments under photo 2





**Photo 4:** Photo taken from the west end of the location, facing southeast. See comments under photo 2



**Photo 5:** Photo taken from the west end of the location, facing south. See comments under photo 2





**Photo 6:** Photo taken from the access road, facing south. Photo shows access road remains and has not been reclaimed per 1004.a





**Photo 7:** Photo taken from the access road, facing north. Photo shows access road remains and has not been reclaimed per 1004.a