

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



photo from access road

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Tank and noxious weeds

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Noxious weeds



Unused equipment

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Only sign on location



Barbed wire piled up on ground with elk tracks by it

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Wire with animal track through and around wire



Full view of tank no labels and wire

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Unused equipment



Weeds and unused equipment

Oxy USA INC.
Api # 05-077-08391
Inspection # 6750080



Unused equipment, Noxious weeds



Unused equipment