

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2019

Submitted Date:

01/25/2019

Document Number:

689500929**FIELD INSPECTION FORM**
 Loc ID 332598 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Candice (Nikki)		candice.graber@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
118846	PIT				-	ARISTOCRAT 32-9 2	EI

**General Comment:**

COGCC Environmental Inspection to determine the status of pit facility ID 118846. Inspection of pit area only; no nearby battery/production facilities or wells inspected.

The pit status has been changed to closed. However, the operator is instructed to submit a Form 27 for site characterization of the historic pit area.

Inspected Facilities									
Facility ID:	118846	Type:	PIT	API Number:	-	Status:		Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Pit location was determined based on aerial imagery. Distressed vegetation as well as a pit-trace depression is present at the historic pit location.

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for for the historic pit area.

Date: 02/23/2019

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**COGCC Comments**

Comment

User

Date

Contact area EPS Nikki Graber with any questions regarding pit status  
C 970-250-0543  
nikki.graber@state.co.us

oakmank

01/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500930	ARISTOCRAT 32-9 2 Pit Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715532">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715532</a>