

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 1



Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)  
Inspection Date: 1/09/2019



Photo # - 2

Crude oil tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 3

Separator and partially buried concrete vault on the south side of production pit #445368



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)  
Inspection Date: 1/09/2019



Photo # - 4

Unused flowline riser



Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 5

Unused flowline riser



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 6

Unused flowline riser



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 7

Unused equipment



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 8

Partially buried concrete vault on the south side of the production pit #445368



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)

Inspection Date: 1/09/2019



Photo # - 9

Partially buried concrete vault outlet on the south side of the pit #445368 and concrete debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Western Operating CO. – Shorty #2 Tank Battery (Location ID 313945)  
Inspection Date: 1/09/2019



Photo # - 10 View south across former production facility from the south side of the production pit #445368

