



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Sabre Beebe
Submission Date:	8/21/2018
Server Receive Date:	8/21/2018
Reference Number:	EIS 003
Location:	State 01-36 35-08 3

Information

Name	Sabre Beebe
Date of work completion:	8/15/2018
Well Name	State 01-36 35-08 3
Select State	Colorado
Work type	COGCC Inspection
Inspection Number	685305163

Action Completed:

Slump on west cut slope was backfilled, seeded and ground matting was installed. The diversion ditch/berm at the base of the slope was rebuilt and extended. A new tank label was installed on the tank secondary containment. Miscellaneous trash/debris was removed and the pad was regraded.

Other *must specify in notes*



Installed diversion ditch




New Sign Install



Other *must specify in notes*



Choose an item.



Choose an item.

