

Inspection Photos

Loc#334753

Operator: Terra

Inspection Number: 692400585

Inspection Date: 1/21/2019





Photo#1:
Overview of Location to Northeast.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosley Loc#334753



Photo#2:
Vegetation in Interim Reclamation areas is well established.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosley Loc#334753



Photo#3:
Erosion is occurring on & sediment migration off, of Cut slope.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosley Loc#334753



Photo#4:
Erosion is occurring on & sediment migration off, of Cut slope.

January 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosley Loc#334753