

Final Reclamation and Stormwater Inspection

January 23, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 327435

Inspection Document #: 674902475

Weld County, CO

NESE Section 36 T3N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /3N66W36
Location ID: 327435



Photo 1. Photo taken from the access road looking into the location, facing East. Operator has performed final reclamation activities. However, the access road lacks uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to cheatgrass.



Photo 2. Photo taken from the well location, facing Northeast. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /3N66W36
Location ID: 327435



Photo 3. Photo taken from the access road, facing Southwest. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /3N66W36
Location ID: 327435



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: KERR MCGEE /3N66W36

Location ID: 327435



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.