

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Photo of location.

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Wellhead sign.

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Riser locked out and tagged

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Unused Equipment on location 53' from well head



Unused Equipment not used for production stored on location

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Unused Equipment on location
Stacked around deadman



Unused Equipment on location
Stacked around deadman

Laramie Energy LLC
Api # 05-077-08426
Inspection # 6775001840



Unused equipment or trash around deadman marker



Hazards, Rods sticking up out of the ground