

Inspection Photos
Location Name: Barbara #2
API: 05-067-09071



Professional Well Services Rig #1.



Tripping in hole in preparations for MIT.

Inspection Photos
Location Name: Barbara #2
API: 05-067-09071



Oily material observed on location. Spot was cleaned up while inspector was on site.



Trailer mounted steel tank used for E and P waste storage.

Inspection Photos
Location Name: Barbara #2
API: 05-067-09071



Steel tank appears to be nearing capacity.



Barbara #2 tank battery.