

# *Inspection Photos*

*Loc#334689*

*Operator: Terra*

*Inspection Number: 692400587*

*Inspection Date: 1/21/2019*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to East.

January 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334689



Photo#2:  
One Anchor Marker down.

January 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334689





**Photo#3:**

Location appears well maintained and Vegetation in Interim Reclamation areas is well established. Some Kochia and Cheat grass was noted at edges of pad, in ditches and at entry.

January 21, 2019



**Photo#4:**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334689