

**Inspection Photos**  
**Location Name: G & D Hanks /27-N Pad**  
**Location #: 453331**



**Photo #1**  
**G & D Hanks /27-N Pad**  
**Flowback inspection**



**Photo #2**  
**G & D Hanks /27-N Pad**  
**Stained soil - Condensate**

**Inspection Photos**  
**Location Name: G & D Hanks /27-N Pad**  
**Location #: 453331**



**Photo #3**  
**G & D Hanks /27-N Pad**  
**Flowback tanks – NOT grounded**



**Photo #4**  
**G & D Hanks /27-N Pad**  
**Internal combustion Transfer pump**  
**Close proximity to hydrocarbon tanks**  
**≈ 15 feet**