

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1150

Location ID: 05-103-09602

Inspection: 679702827



Photo 1. Location looking northeast.



Photo 2. Tank liner is torn.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources