

Inspection Photos
Location Name: NIES #6-1
Location ID: 320327



Photo 1 WH/PU

Photo 2 location has plowed field around it no erosion

Inspection Photos
Location Name: NIES #6-1
Location ID: 320327



Photo 3 TNK BTRY trach (roll of cable) tank not painted

Photo 4 horizontal separator not painted

Inspection Photos
Location Name: NIES #6-1
Location ID: 320327



Colorado Oil and Gas Conservation Commission
39.9059, -104.5878, 1585.4m
Jan 29, 2019 11:36:41 AM

Photo open top tank, trash (truck fenders)