

Interim Reclamation and Stormwater Inspection

January 28, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 423984

Inspection Document #: 682404474

Weld County, CO

SESE Section 4 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pergamos /4-44-7-60
Location ID: 423984



Photo 1. Photo taken from the entrance of the location, facing East. Photo illustrates the southern well pad. Operator has failed to perform interim reclamation.



Photo 2. Photo taken from the entrance of the location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /4-44-7-60
Location ID: 423984



Photo 3. Photo taken from the northwestern well pad, facing East. Photo illustrates unmanaged weeds along the southern fill slope of the topsoil stockpile. Operator shall control weeds and weed debris per Rule 603.f. and comply with Rule 1002.c.