

**Inspection Photos**  
**Location Name: HSR-WIEDMAN 14-20**  
**Location ID: 330452**



**Photo 1: Wellhead**



**Photo 2: Tank Battery**

**Inspection Photos**  
**Location Name: HSR-WIEDEMAN 14-20**  
**Location ID: 330452**



**Photo 3: Incorrect information on Produced Water sign.**



**Photo 4: Appears to be stained soil from mechanical condition on east separator.**