

Final Reclamation Inspection

January 28, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 424579

Inspection Document #: 682404476

Weld County, CO

NWNW Section 8 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 1. Photo taken from the entrance of the location, facing East. Photo taken from the locked gate entrance to the location. Operator constructed the location but never drilled the proposed well. Operator has instead turned the location into a storage yard. Spills were observed throughout the location outside of containment, as well as unmanaged weeds. Operator shall clean up all spills, control/remove weeds, remove all equipment, and perform Final Reclamation.



Photo 2. Photo taken from the northwestern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 3. Photo taken from the northwestern location, facing Southwest. See comments under Photo 1.



Photo 4. Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 5. Photo taken from the southwestern location, facing South. See comments under Photo 1.



Photo 6. Photo taken from the southwestern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 7. Photo taken from the southwestern location, facing South. See comments under Photo 1.



Photo 8. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 9. Photo taken from the southern location, facing East. See comments under Photo 1.



Photo 10. Photo taken from the southeastern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 11. Photo taken from the southeastern location, facing North. See comments under Photo 1.



Photo 12. Photo taken from the eastern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 13. Photo taken from the eastern location, facing East. See comments under Photo 1.



Photo 14. Photo taken from the northeastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 15. Photo taken from the northeastern location. See comments under Photo 1.



Photo 16. Photo taken from the northeastern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 17. Photo taken from the western location, facing South. Weeds were observed throughout the topsoil stockpile.