

Inspection Photos

1/31/2019

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 436809

Inspection Doc. Number: 682504465

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 436809




Photo 1: 2013 Google earth aerial imagery. Photo shows disturbance area for the location. A disturbance area of 7.19 acres was measured using a Trimble Juno 3B handheld device. This exceeds the permitted disturbance area of 6.8 acres.



Photo 2: Photo taken from the south end of the location, facing west. Photos 2- 5 provide and overview of the location from west, northwest, northeast to east. Photos also show interim reclamation has not been conducted in accordance with COGCC rule 1003.

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 436809



Photo 3: See comments under photo 2.





Photo 4: See comments under photo 2.



Photo 5: See comments under photo 2.

Inspection Photos
Operator: VERDAD RESOURCES LLC - 10651
Location ID: 436809



Photo 6: Photo taken from the southeast corner of the location, facing northwest. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003



Photo 7: Photo taken from the southeast corner of the location, facing north. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003



Photo 8: Photo taken from the northeast corner of the location, facing south. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003



Photo 9: Photo taken from the northeast corner of the location, facing southwest. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003



Photo 10: Photo taken from the northeast corner of the location, facing west. Photo shows interim reclamation has not been conducted in accordance with COGCC rule 1003