

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2019

Submitted Date:

02/01/2019

Document Number:

689702530**FIELD INSPECTION FORM**Loc ID 335903 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

24 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292392	WELL	PR	02/18/2011	GW	045-14709	CC 697-17-19B	PR
293501	WELL	PR	09/20/2008	GW	045-15012	CC 697-17-25B	PR
293502	WELL	PR	12/20/2008	GW	045-15013	CC 697-17-33A	PR
294084	WELL	PR	06/01/2017	GW	045-15242	CC 697-18-47B	PR
294095	WELL	PR	03/31/2012	GW	045-15245	CC 697-17-27B	PR
294097	WELL	PR	08/23/2008	GW	045-15246	CC 697-17-25A	PR
294098	WELL	PR	12/08/2008	GW	045-15247	CC 697-17-35A	PR
294099	WELL	PR	10/01/2013	GW	045-15248	CC 697-17-35B	PR
294100	WELL	PR	09/06/2011	GW	045-15249	CC 697-17-44	PR
294102	WELL	PR	10/14/2008	GW	045-15250	CC 697-18-56A	PR
294104	WELL	PR	07/01/2014	GW	045-15251	CC 697-18-64B	PR
294107	WELL	PR	04/25/2012	GW	045-15252	CC 697-17-52	PR
294111	WELL	PR	10/14/2008	GW	045-15253	CC 697-18-47A	PR
294118	WELL	PR	10/11/2008	GW	045-15260	CC 697-17-33B	PR
294119	WELL	PR	12/20/2013	GW	045-15261	CC 697-17-50	PR
294120	WELL	PR	12/18/2008	GW	045-15262	CC 697-17-41A	PR
294121	WELL	PR	01/21/2009	GW	045-15263	CC 697-17-41B	PR
294194	WELL	PR	12/08/2008	GW	045-15313	CASCADE CREEK 697-19-08A	PR
294195	WELL	PR	10/14/2008	GW	045-15314	CC 697-18-64A	PR
294196	WELL	PR	10/14/2008	GW	045-15315	CC 697-18-39B	PR
294362	WELL	PR	10/14/2008	GW	045-15399	CC 697-18-56B	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	292392	Type:	WELL	API Number:	045-14709	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293501	Type:	WELL	API Number:	045-15012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293502	Type:	WELL	API Number:	045-15013	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294084	Type:	WELL	API Number:	045-15242	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294095	Type:	WELL	API Number:	045-15245	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294097	Type:	WELL	API Number:	045-15246	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294098	Type:	WELL	API Number:	045-15247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294099	Type:	WELL	API Number:	045-15248	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	294100	Type:	WELL	API Number:	045-15249	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294102	Type:	WELL	API Number:	045-15250	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294104	Type:	WELL	API Number:	045-15251	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294107	Type:	WELL	API Number:	045-15252	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294111	Type:	WELL	API Number:	045-15253	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294118	Type:	WELL	API Number:	045-15260	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294119	Type:	WELL	API Number:	045-15261	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294120	Type:	WELL	API Number:	045-15262	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	294121	Type:	WELL	API Number:	045-15263	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294194	Type:	WELL	API Number:	045-15313	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294195	Type:	WELL	API Number:	045-15314	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294196	Type:	WELL	API Number:	045-15315	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294362	Type:	WELL	API Number:	045-15399	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Ditches	Pass			
		Compaction	Pass			
Compaction	Pass					
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702531	Inspection 689702530 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4723174