

Inspection Photo (s)
Federal 32D
API # 05-045-19680
Inspection # 689303136



Location Photo #1



Location Photo #2

Inspection Photo (s)
Federal 32D
API # 05-045-19680
Inspection # 689303136



Location Photo #3



Location Photo #4, Stained material near scrubber pot not cleaned.

Inspection Photo (s)
Federal 32D
API # 05-045-19680
Inspection # 689303136



Location Photo #5, Stained material near scrubber pot not cleaned.



Location Photo #6, Stained material near scrubber pot not cleaned.

Inspection Photo (s)
Federal 32D
API # 05-045-19680
Inspection # 689303136



Location Photo #7, Stained material near scrubber pot.



Location Photo #8, Stained material near scrubber pot not cleaned

Inspection Photo (s)
Federal 32D
API # 05-045-19680
Inspection # 689303136



Location Photo #9, Stained material near scrubber pot not cleaned.