

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #1



Location Photo #2

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #3



Location Photo #4

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



**Location Photo #5, Released/spilled
condensate.**



**Location Photo #6, Released/spilled
condensate.**

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #7, Released/spilled condensate.



Location Photo #8, Released/spilled condensate.

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #9, Released/spilled condensate.



Location Photo #10, Released/spilled condensate.

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



**Location Photo #11, Released/spilled
condensate.**



**Location Photo #12, Released/spilled
condensate.**

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #13, Released/spilled condensate.



Location Photo #14, Released/spilled condensate.

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



**Location Photo #15, Released/spilled
condensate.**



**Location Photo #16, Released/spilled
condensate.**

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689303142



Location Photo #17, Released/spilled condensate.



Location Photo #18, Released/spilled condensate.