

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 318247

Inspection Document #: 674902471

Weld County, CO

SESE Section 31 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /1N65W31

Location ID: 318247



Photo 1. Photo taken from the access location, facing West. Appears the Operator has performed final reclamation activities with the evidence of seed preparations.



Photo 2. Photo taken from the access road off CR 2, facing South. Access road remains on location.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /1N65W31

Location ID: 318247



Photo 3. Photo taken from the location, facing East. Photo depicts equipment on location. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. See comments from Photo 1.