

Final Reclamation and Stormwater Inspection

January 29, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 317723

Inspection Document #: 674902521

Weld County, CO

SESW Section 16 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE /1N65W16

Location ID: 317723



Photo 1. Photo taken from the access road looking into the location, facing North. Appears Operator has performed recent final reclamation activities with the evidence of straw crimped mulch. However parts of the access road have not been reclaimed.



Photo 2. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE /1N65W16

Location ID: 317723



Photo 3. Photo taken from the location, facing Southwest. See comments from Photo 1.



Photo 4. Photo taken from the well location. Photo depicts equipment left on site.

Inspection Photos

Location Name: KERR MCGEE /1N65W16

Location ID: 317723



Photo 5. Photo taken from the access road, facing South. Appears part of the road is left



Photo 6. Photo taken from the access road, facing South. See comments from Photo 1.