

Inspection Photos

2/04/2019

Operator: MALLARD EXPLORATION LLC # 10670

Location ID: 438327

Inspection Doc. Number: 682504486

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest corner of the location, facing north. Photo shows areas not needed for production appears to have been reduced. Interim reclamation activities appear to be in process, however seeding activities and stabilization/erosion controls do not yet appear to have been implemented. Corrective action will remain applicable until addressed in its entirety.



Photo 2: Photo taken from the southwest corner of the location, facing northeast. See comments under photo 1.



Photo 3: Photo taken from the southwest corner of the location, facing east. See comments under photo 1.



Photo 4: Photo taken from the north end of the location. Photo shows areas not needed for production appears to have been reduced. Interim reclamation activities appear to be in process, however seeding activities and stabilization/erosion controls do not yet appear to have been implemented. Corrective action will remain applicable until addressed in its entirety.