

# Inspection Photos

2/04/2019

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327492

Inspection Doc. Number: 682504490  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 327492



**Photo 1:** Photo taken from the south end of the battery location facing north. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 2:** Photo taken from the south end of the battery location facing north. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 3:** Photo taken from the battery location facing east. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 4:** Photo taken from the battery location facing east. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 5:** Photo taken from the battery location, facing. Photo shows tank laying on side. Base of tank appears to have a hole. Photo also shows contaminated soils at tank base have not been remediated/removed.



**Photo 6:** Photo taken from the battery location facing southwest. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 7:** Photo taken from the battery location facing east. Photo show operator has failed to remove equipment and conduct reclamation of the location.



**Photo 8:** Photo taken from the battery location facing northeast. Photo show operator has failed to remove equipment and conduct reclamation of the location..



**Photo 9:** 2013 Google Earth aerial imagery. Photo shows aerial image of the tank battery and various equipment on site.