

# Inspection Photos

2/04/2019

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327573

Inspection Doc. Number: 682504492  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the south end of the battery location facing northwest. Previous inspection documented that location had not been cross-ripped in accordance to COGCC 1000 series rules. Photo shows location remains unchanged since previous inspection; compaction alleviation has not been conducted in accordance with reclamation requirements.



**Photo 2:** Photo taken from the south end of the battery location facing north. See comments under photo 1.





**Photo 3:** Photo taken from the south end of the battery location facing northeast. See comments under photo 1.





**Photo 4:** Photo taken from the access road, facing north. Access road appears unchanged since previous inspection; Unable to find evidence that compaction alleviation has been conducted in accordance with 1004.a on access road.