



Photo # - 1

Location Name: Schneider Energy Services, Inc. – Veeman 23-5 (Plugging)

Inspection Date: 1/09/2019



Photo # - 2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo # - 3

Produce water tank at the shared Veeman 23-5 and Smith #1 tank battery



Photo # - 4

Capped risers associated with the removal of the Veeman 23-5 separator



Photo # - 5

Capped risers associated with the removal of the Veeman 23-5 separator



Photo # - 6

Capped risers associated with the removal of the Veeman 23-5 separator



Photo # - 7

View north at Veeman 23-5 and Smith #1 tank battery