

## January 18, 2019 Field Photos

Location Name: Bargath 16" Pipeline Release

Spill/Release ID #460855

Inspection Dates: January 18, 2019 – January 28, 2019



**Photo #1 – Overview of flowline excavation and area impacted by condensate spray from west side of Co Rd 215 (looking southwest).**



**Photo #2 – View into pipeline excavation from east side. Note exposed 16" pipeline and condensate present in base of excavation.**

## January 18, 2019 Field Photos

Location Name: Bargath 16" Pipeline Release

Spill/Release ID #460855

Inspection Dates: January 18, 2019 – January 28, 2019



**Photo #3 – Visible hydrocarbon impacts along irrigation ditch southeast of pipeline excavation. Note that soil and vegetation on either side of ditch were sprayed by condensate by Spill/Release ID #460855.**



**Photo #4 – Absorbent booms had been installed inside of irrigation ditch from previous photo along a fenceline located approximately 300' southeast of pipeline excavation.**



## January 18, 2019 Field Photos

Location Name: Bargath 16" Pipeline Release

Spill/Release ID #460855

Inspection Dates: January 18, 2019 – January 28, 2019



**Photo #5 – Hydrocarbon-impacted snow, vegetation, and soil located southeast of pipeline excavation.**



**Photo #6 - Hydrocarbon-impacted snow, vegetation, and soil located southwest of pipeline excavation.**

## January 18, 2019 Field Photos

Location Name: Bargath 16" Pipeline Release

Spill/Release ID #460855

Inspection Dates: January 18, 2019 – January 28, 2019



**Photo #7 – Confluence area of surface-water runoff and Parachute Creek, located ~670' southwest of pipeline excavation. Note that hydrocarbon odors and a hydrocarbon sheen on surface water were observed in this location.**



**Photo #8 – Close up shot of hydrocarbon sheen observed in confluence area from previous photo.**