

Inspection Photos

Loc#335678

Operator: Ursa

Inspection Number: 692400637

Inspection Date: 1/31/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

January 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335678



Photo#2:
West Access road ditch from point where it exits
location.

January 31, 2019



Photo#3:
Wattles used as check dams.



Photo#4:
Area where SW drains offsite into waterway
area.

January 31, 2019




Photo#5:
Area where SW drains offsite into waterway
area.



Photo#6:
Vegetation establishment on slopes is largely unsuccessful. Netting has become Debris.

January 31, 2019



Photo#7:
Vegetation establishment on slopes is largely unsuccessful. Netting has become Debris.



Photo#8:
Material handling & Spill Prevention addressed
in Environmental Inspection.

January 31, 2019

Photo#9:
Material handling & Spill Prevention addressed
in Environmental Inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335678