

Inspection Photos
Location Name: OTTER 44-2
API #: 05-071-06678
Insp. Doc. # 695100144



PHOTO 1: WELLHEAD/UNUSED EQUIPMENT



**PHOTO 2: WELL SIGN/METER HOUSE/EMERGENCY CONTACT
NUMBER NOT LEGIBLE**

Inspection Photos
Location Name: OTTER 44-2
API #: 05-071-06678
Insp. Doc. # 695100144



PHOTO 3: NFPA LABEL POSTED



PHOTO 4: GAS METER CALIBRATION LOG UNDATED