

Inspected Facilities

Facility ID: 456964 Type: WELL API Number: 123-47683 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Liberty oilfield services Stimulation Type: HYDRAULIC FRAC
Other: _____

Observation:

Maximum Casing Recorded: _____ PSI Tubing: _____
Surface: 0 Intermediate: _____
Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
Bradenhead Psi: -12 Frac Flow Back: _____ Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401259	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729994