

Inspection Photos
Location Name: LORECITO 7-6
API #: 05-071-08147
Insp. Doc. # 695100160



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: LORECITO 7-6
API #: 05-071-08147
Insp. Doc. # 695100160



PHOTO 3: WELLHEAD IS OPEN TO ATMOSPHERE AND NOT LO/TO.



PHOTO 4: UNUSED UNMARKED RISER NOT LO/TO, UNUSED EQUIPMENT STORED ON LOCATION.

Inspection Photos
Location Name: LORECITO 7-6
API #: 05-071-08147
Insp. Doc. # 695100160



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION