

Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: PDC ENERGY INC – 69175

Location ID: 333319

Inspection Document #: 674902547

Weld County, CO

SESW Section 2 T4N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC/4N65W2
Location ID: 333319



Photo 1. Photo taken from the access road looking into the location, facing North. Appears Operator has not performed any final reclamation activities with equipment and gravel still on location.



Photo 2. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos
Location Name: PDC ENERGY INC/4N65W2
Location ID: 333319



Photo 3. Photo taken from the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing West. Photo depicts equipment left on site.