

# Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 327446

Inspection Document #: 674902548

Weld County, CO

SENW Section 22 T3N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: NOBLE ENERGY INC /3N65W22

Location ID: 327446



**Photo 1.** Photo taken from the location, facing East. Appears Operator has not performed any final reclamation activities with equipment and gravel still on location.



**Photo 2.** Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC /3N65W22

Location ID: 327446



**Photo 3.** Photo taken from the location, facing Northeast. See comments from Photo 1.



**Photo 4.** Photo taken from the location, facing South. See comments from Photo 1.