

# Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 327797

Inspection Document #: 674902553

Weld County, CO

SESE Section 21 T3N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE /3N65W21

Location ID: 327797



**Photo 1.** Photo taken from the access road looking into the location, facing West. Appears the Operator has performed final reclamation activities. Well location and access road appear reflective of adjacent reference crop areas.



**Photo 2.** Photo taken from the location, facing West. See comments from Photo 1.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE /3N65W21

Location ID: 327797



**Photo 3.** Photo taken from the location, facing East. See comments from Photo 1.



**Photo 4.** Photo taken from the access road, facing East. See comments from Photo 1.