

Inspection Photos
Location Name: John A Kunzman #2
Location ID: 332891



Photo 1WH



Photo 2 electric panel

Inspection Photos
Location Name: John A Kunzman #2
Location ID: 332891



Colorado Oil and Gas Conservation Commission
40.15811, -104.80363, 1468.2m
Feb 12, 2019 11:17:39 AM

Photo 3 stained soil 2" production line



Colorado Oil and Gas Conservation Commission
40.15812, -104.80362, 1467.5m
Feb 12, 2019 11:17:45 AM

Photo 4 stained soil 2" production line

Inspection Photos
Location Name: John A Kunzman #2
Location ID: 332891



Photo 5 gear box leaking on cement pad



Photo 6 PU gear box leaking

Inspection Photos
Location Name: John A Kunzman #2
Location ID: 332891



Photo 7 stained soil 2" production line

