

Stormwater Inspection

February 13, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 321432

Inspection Document #: 682404505

Boulder County, CO

NENW Section 34 T2N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MCCARTY #MB 34-3
Location ID: 321432



Photo 1. Photo taken from the entrance of the location off Niwot Rd., facing South. No tracking device BMP's installed or not adequately maintained to prevent track of material offsite.

Inspection Photos
Location Name: MCCARTY #MB 34-3
Location ID: 321432



Photo 2. Photo taken from the entrance of the location off Niwot Rd., facing East. See comments under Photo 1.