

# *Inspection Photos*

*API#103-08172*

*Operator: Rio Mesa Resources*

*Inspection Number: 692400511*

*Inspection Date: 12/27/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View of Location to Northwest; insert is of Utilities that remain installed.

December 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Rio Mesa Resources PA Newton API#103-08172



Photo#2:  
Areas that have not been re-contoured; insert is of stained soil

December 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Rio Mesa Resources PA Newton API#103-08172



Photo#3:  
Concrete slab that remains on Location.

December 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Rio Mesa Resources PA Newton API#103-08172