

Location Name: White AM 1    API: 017-06661    Inspection Date: 2/13/2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: White AM 1    API: 017-06661    Inspection Date: 2/13/2019



Feb 13, 2019 10:08:35  
38.82209N 102.05981W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: White AM 1    API: 017-06661    Inspection Date: 2/13/2019



Valve that was observed to be venting during my last inspection has been removed leaving this open pipe that was observed to be actively venting methane gas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: White AM 1    API: 017-06661    Inspection Date: 2/13/2019



Feb 13, 2019 10:08:43  
38.82210N 102.05984W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: White AM 1    API: 017-06661    Inspection Date: 2/13/2019



Methane gas is being vented.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources