

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

682600639**FIELD INSPECTION FORM**

Loc ID 321660 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 51065Name of Operator: LOEB LLC* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	
Middagh, Jesse	815-556-0756	jesse@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207708	WELL	PR	06/26/1998	OW	017-06643	WHITE 'AG' 2	EI

General Comment:

Environmental inspection to document status of any gas venting from wellhead. Inspection found bull plug installed but gas was heard leaking from valve and a 4 gas meter detected methane gas. COGCC video recorded methane detection however video could not be uploaded to inspection. Video available for email via request.

Operator should ensure that all bull plugs and valves on all wells are secured properly to stop gas venting unintentionally.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas observed to be venting from white bull plug pictured in the attached photos. Methane was detected with a 4 gas meter.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/15/2019

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 207708 Type: WELL API Number: 017-06643 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600640	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735422
682600641	Leaking gas video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735423