

Construction and Stormwater Inspection

February 8, 2019

Operator: ELEVATION MIDSTREAM LLC – 10687

Location ID: 460416

Inspection Document #: 674902557

Weld County, CO

NE Section 30 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 1. Photo taken from the access road looking into the location off CR 15, facing Northwest. Operator has installed gravel potentially to limit tracking onto the county road.



Photo 2. Photo taken from the location, facing East. Appears the operator has a stockpile stored on location.

Inspection Photos

Location Name: NOBLE ENERGY INC /1N67W30

Location ID: 460416



Photo 3. Photo taken from the location, facing East. Photo depicts equipment on site and storage pile. No other construction operations were observed on location at this time.



Photo 4. Photo taken from the location, facing North. Photo depicts sound wall that is already installed on the North side of the location along CR 6.